

## POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION AND PRELIMINARY ASSESSMENT

REGION

SITE NUMBER (to be assigned by Hq)

۷I

TX-05436

NOTE: This form is completed for each potential hazardous waste site to help set priorities for site inspection. The information submitted on this form is based on available records and may be updated on subsequent forms as a result of additional inquiries and on-site inspections.

GENERAL INSTRUCTIONS: Complete Sections I and III through X as completely as possible before Section II (Preliminary Assessment). File this form in the Regional Hazardous Waste Log File and submit a copy to: U.S. Environmental Protection Agency; Site Tracking System; Hazardous Waste Enforcement Task Force (EN-335); 401 M St., SW; Washington, DC 20460.

<u>,</u>			
	NTIFICATION		
A. SITE NAME		other identifier)	
THOMAS STEEL DRUMS	2517 NE 3	5th	
C. CITY	D. STATE	E. ZIP CODE	F. COUNTY NAME
Fort Worth	TX	76111	Tarrant`
G.OWNER/OPERATOR (If known) 1. NAME Jim Boase - Plant Manager			
Curtis Thomas - Personal			2. TELEPHONE NUMBER (817)838-6891
Curcis monas - reisonar			(0.,,000
H. TYPE OF OWNERSHIP			
1. FEDERAL 2. STATE 3. COUNTY 4. MUNIC	CIPAL X 5.	PRIVATE 6. 1	UNKNOWN
I. SITE DESCRIPTION FIRM reconditions old steel	drums. So	me residue i	<del>n barrels is allegedly -</del>
sent to an unidentified landfill; some is du	umped on t	:he ground(5 <i>€</i> ,	EPHOTO#2)ON SITE;
REMAINDER of residue in drums is incinerate	ed.		•
J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.) (	`itizen's	complaint -	K. DATE IDENTIFIED
Ted & Fred Polser, Polser Marble Co., compl	aint made	to Texas Air	Control (mo, day, & yr.)
Roard			6/6/80
L. PRINCIPAL STATE CONTACT Jim Webb, Texas Air I	Poll Cont	rol - Tarran	t Co. (817)870-7281
1. NAME	orr. conc	io, jairan	2. TELEPHONE NUMBER
Charles Gill, Supervisor Texas Dept. Water F	Resources	•	(214)298-6171
II. PRELIMINARY ASSESSME	NT (complete t	his section last)	L
A. APPARENT SERIOUSNESS OF PROBLEM			00000000
☐1. HIGH ☐2. MEDIUM [X]3. LOW ☐4. NONE	<b>┌</b> 5. 1	UNKNOWN	90068259
B. RECOMMENDATION		<del></del> :	<b>                                    </b>
1. NO ACTION NEEDED (no hazard)	2. IMMER	DIATE SITE INSPEC	TION NEEDED
The Market Marada (no marada)	a. TEN	TATIVELY SCHEDU	ILED FOR
3. SITE INSPECTION NEEDED			
B. TENTATIVELY SCHEDULED FOR:	b. WILI	L BE PERFORMED I	BY:
	•		
b. WILL BE PERFORMED BY:	TXTA SITE I	NSPECTION NEEDS	ED (low priority)
· · .			ling inspection be con-
ducted to determine whether drum residues ar			ting thispection be con-
C. PREPARER INFORMATION	e migraci	ily of 1-5 (ce.	<del></del>
	12. TELE	PHONE NUMBER	3. DATE (mo., day, & yr.)
1. NAME Barry Nash Barry Nash		742-4521	10/13/80
III. SITE IN	FORMATION		<u></u>
A. SITE STATUS			
X   1. ACTIVE (Those industrial or municipal sites which are being used   2. INACTIVE (Those sites which no longer receive	(Those sites t	l (specify): hat include such inc	idents like "midnight dumping" where
for waste treatment, storage, or disposal wastes.) on a continuing basis, even if infre—	no regular or c	continuing use of the	site for waste disposal has occurred.)
quently.)	•		
		· · · · · · · · · · · · · · · · · · ·	
B. IS GENERATOR ON SITE?			
1. NO 2. YES (specify general	rator's fow—digi	it SIC Code):	
<u> </u>			
C. AREA OF SITE (in acres)  D. IF APPARENT SERIOUSN		·	
1. LATITUDE (degminsec	:•)		DE (deg.—min.—sec.)
2-3 Acres 32 <sup>0</sup> 48' 50" N		97 <sup>0</sup> 1	18' 8" W
E. ARE THERE BUILDINGS ON THE SITE!		<del></del>	
`□ï. NO 🔯 2. YES (*pocity): Incinerators, pai	nt shops		
		·	<del></del>

## V. WASTE RELATED INFORMATION (continued)

3. LIST SUBSTANCES OF GREATEST CONCERN WHICH MAY BE ON THE SITE (place in descending order of hazard).

TACB Analysis: lead, titanium, barium, manganese, zinc, paint, solvents, unknown chemicals.

4. ADDITIONAL COMMENTS OR NARRATIVE DESCRIPTION OF SITUATION KNOWN OR REPORTED TO EXIST AT THE SITE. Barrels come from several sources. Most materials are paints, inks and solvents. Jim Webb, TACB states that metal container has caught fire in the past, possibly due to incompatible wastes.

	<del>,</del>	VI. HAZ	ARD DESCRIPTI	UN
A. TYPE OF HAZARD	B. POTEN- TIAL HAZARD (merk 'X')	C. ALLEGED INCIDENT (mark 'X')	D. DATE OF INCIDENT (mo.,day,yr.)	E. REMARKS
1. NO HAZARD				
2. HUMAN HEALTH				
3. NON-WORKER INJURY/EXPOSURE			·	
4. WORKER INJURY				
8. CONTAMINATION B. OF WATER SUPPLY				
6. OF FOOD CHAIN				
7 OF GROUND WATER			!	
8. CONTAMINATION OF SURFACE WATER	Х			Potential for dumped residue to reach storm sewers during rainfall.
9. DAMAGE TO FLORA/FAUNA				·
10. FISH KILL				
11. CONTAMINATION		Х	Numerous Times	Texas Air Control Board has fined company several times.
12. NOTICEABLE ODORS		Х	Numerous Times	Texas Air Control Board has re- ceived several citizen complaints.
18. CONTAMINATION OF SOIL				
14. PROPERTY DAMAGE			·	
15. FIRE OR EXPLOSION		Х	UNKNOWN	Container of wastes has caught fire more than once. (Jim Webb, TACB)
16. SPILLS/LEAKING CONTAINERS/ RUNOFF/STANDING LIQUIDS	Х			Residue is alleged to be dumped carelessly on to ground.
17. SEWER, STORM DRAIN PROBLEMS	X			Potential problem during rainfall.
18. EROSION PROBLEMS		,		
19. INADEQUATE SECURITY				
20. INCOMPATIBLE WASTES	Х			Fire may have been due to incompati wastes.
21. MIDNIGHT DUMPING				
2 2. OTHER (specify):	X			Destination of collected barrel residue is unknown.

NOTE: Based on the information in Sections III through X, fill out the Preliminary Assessment (Section II) information on the first page of this form.

TACB

UNKNOWN

EPA Form T2070-2 (10-79)

Enforcement Case

PAGE 4 OF 4

Primary problem seems to be air pollution due to inadequate facilities to completely combust residue and in Sufficient draft to clear away emissions. A recon conducted by two members of the FIT team on October 2, 1980 indicated no current runoff problems. At the time of the visit, however, a potential problem was observed which may have been caused by previous runoffs from the site (See photo # 5).


Fines paid by Thomas Steel Drum. Conditions remained unimproved.

			1	
The second	CE. TE. TE.			
The second second			in the second	
NAME OF				
	4.0			
其很多为。	1.11			
(1) 人		A STATE		
	Photo	1		

Barry Nash Dege Saul
Date / Time / Direction
10/2/80 1430 East
Comments: Pit for unknown
purpose along west side of
property near Mapleleaf St.

,	
$\int_{\mathbb{R}^{n}}$	
	1

Photographer / Witness
Barry Nash Deng ! Only
Date / Time / Direction
10/2/80 1435 South
Comments: Unidentified waste
near incinerator.




Photographer / Witness

Barry Nash

Date / Time / Direction

10/2/80 1440 North

Comments: Drums on site




Photographer / Witness

Barry Nash Deus Date / Time / Direction

10/2/80 1445 Northwest

Comments: Trucks loaded

With drums on site.



Photographer / Witness

Barry Nach Denyel. Sulf

Date / Time / Direction

10/2/80 1450 West

Comments: Oreen residue


along 35th Street, from

Unknown origin. Appears

to originate on site Residue

15 about 15 feet from the

property line (ence.



Barry Nash / Bey ! Duly
Date / Time / Direction
10/2/80 1455 East

Comments: Drums on Northwest
Corner of site, containing
Aried paint

Photographer / Witness()

Photo 6

TX5436

EMERGENCY · NUMBERS FOR	I-T WORTH (AREA (OI	)E 81
RE THOMAS STEEL DRUMS		
	· · · · · · · · · · · · · · · · · · ·	<del></del>
POISON CONTROL CENTER	336-6611	
JOHN PETER SMITH HOSPITAL	921 - 3431	
FIRE DEPARTMENT	332-2131	
AMBULANCE	335 = [213]	
POLICE	335 4222	